

A line drawing showing two rectangular units. The unit on the left has a circular connector on its top surface and a multi-pin connector on its front. The unit on the right has a circular connector on its front surface. A cable is shown connecting the multi-pin connector of the left unit to the circular connector of the right unit.

A line drawing showing the connection of the power supply unit to the control unit. The power supply unit is on the left, and the control unit is on the right. They are connected by a cable. The power supply unit has a terminal block with a screw terminal and a push-button terminal. The control unit has a terminal block with a screw terminal and a push-button terminal. The cable connects the screw terminal of the power supply unit to the screw terminal of the control unit, and the push-button terminal of the power supply unit to the push-button terminal of the control unit.