

An isometric drawing of a mechanical component. It features a U-shaped notch on the left side. On the right side, there is a vertical plate with a threaded hole. The top surface has several circular features, possibly holes or mounting points. The drawing is a black and white line art.

An isometric drawing of a mechanical component. It features a U-shaped notch on the front face. On the right side, there is a vertical plate with a threaded hole. The top surface has several small circular features, possibly holes or mounting points. The drawing is a technical representation of a 3D object.

This diagram shows an exploded view of a mechanical assembly. It consists of a base plate with four mounting holes, a central bracket with a U-shaped cutout, and a bolt. The bolt is shown passing through the central bracket and the base plate, secured with a nut and washer. The assembly is shown in a perspective view.

An isometric drawing of a mechanical component. It features a U-shaped cutout on the front face. On the right side, there is a vertical threaded hole. The top surface has several small circular features, possibly holes or mounting points. The part is shown in a three-quarter view, highlighting its 3D structure.

This diagram shows an exploded view of a mechanical assembly. It consists of three main components: a base plate, a bracket, and a bolt. The base plate is a rectangular plate with several holes. The bracket is a U-shaped component that fits into the base plate. The bolt is used to secure the bracket to the base plate.

This diagram shows an exploded view of a mechanical assembly. It consists of a base plate with two circular holes, a central block with a T-shaped cross-section, and a clamping mechanism. The clamping mechanism includes a bolt and a nut, which are shown being inserted into the central block to secure it to the base plate.

Technical drawing of a mechanical part, likely a bracket or support, showing a side view with a U-shaped cutout and a threaded hole.