

This diagram shows an exploded view of a mechanical assembly. It consists of three main components: a base plate, a central bracket, and a bolt. The base plate is a rectangular block with several circular holes. The central bracket is a U-shaped component that fits into the base plate. The bolt is shown passing through the bracket and the base plate, secured with a nut. The components are shown in a perspective view, with the bolt and nut positioned to the right of the bracket.

Technical drawing of a mechanical part, likely a bracket or support, showing a side view with a bolt and nut assembly.

This diagram shows an exploded view of a mechanical assembly. It consists of three main components: a base plate, a central bracket, and a bolt. The base plate is a rectangular block with several holes. The central bracket is a U-shaped component that fits into the base plate. The bolt is used to secure the bracket to the base plate.

Technical drawing of a mechanical part, likely a bracket or support, showing a side view with a bolt and nut assembly.

This diagram shows an exploded view of a mechanical assembly. It consists of a base plate with a central slot, a bracket that fits into the slot, and a bolt that secures the bracket to the base plate. The bolt is shown passing through the bracket and the base plate, with a nut on the other side.

This diagram shows an exploded view of a mechanical assembly. It consists of three main components: a base plate, a bracket, and a bolt. The base plate is a rectangular block with several circular holes. The bracket is a U-shaped component that fits into a slot on the base plate. The bolt is used to secure the bracket to the base plate.

This diagram shows an exploded view of a mechanical assembly. It consists of a base plate with a central rectangular cutout, a central block with a matching protrusion, and a bolt. The bolt is shown passing through the central block and the base plate, secured with a nut and washer. The assembly is shown in a perspective view.

This isometric drawing shows a mechanical component with a U-shaped notch on its front face. A threaded hole is located on the right side of the front face. The top surface has several circular features, possibly holes or mounting points. The part is shown from a perspective that highlights its three-dimensional structure.